

序号	报告编号	发布日期	结论	影像资料
21	GX-B1324/21-2-25006~25008	2025. 4. 8	所检项目合格。	
22	GX-B1328/20-2-25037	2025. 4. 8	本次共检绝缘手套18只，18只绝缘手套合格。	


23	GX-B1328/20-2-25038	2025. 4. 8	本次共检绝缘靴 20只，20只绝缘靴合格。	 2025/3/22
24	GX-B1350/21-2-25011	2025. 4. 9	所检项目合格。	 2025/03/27

25	GX-B1350/21-2-25012	2025. 4. 9	本次共检验接地装置5处，5处所检项目合格。 。	
26	GX-B1313/21-2-25084~25085	2025. 4. 9	本次共检电力变压器2台，2台所检项目合格。 。	

27	GX-B1313/21-2-25089~25091	2025. 4. 9	本次共检电力变压器3台，3台所检项目合格。 。	
28	GX-B1451/20-2-25216~25228	2025. 4. 8	本次共检高压开关柜13台，13台高压开关柜所检项目合格。	

29	GX-B1451/20-2-25229~25243	2025. 4. 8	本次共检高压开关柜15台，15台高压开关柜所检项目合格。	
30	GX-B1322/21-2-25124~25131	2025. 4. 8	本次共检验电力电缆8条，8条所检项目合格。	

31	GX-B1322/21-2-25132~25137	2025. 4. 8	本次共检验电力电缆6条，6条所检项目合格。	
32	GX-B1451/20-2-25135~25146	2025. 4. 10	所检项目合格。	

33	GX-B1322/21-2-25091~25119	2025. 4. 10	所检项目合格。		
34	GX-B1313/21-2-25138~25149	2025. 4. 10	所检项目合格。		

35	GX-B1313/21-2-25069~25079	2025. 4. 10	所检项目合格。	
36	GX-B1313/21-2-25080~25081	2025. 4. 10	所检项目合格。	

37	GX-B1598/24-2-25049	2025. 4. 10	实测钢丝绳有效截面积 损失百分比最大为 0.97%， 小于5%为正常。		
38	GX-B1598/24-2-25050	2025. 4. 10	实测钢丝绳有效截面积 损失百分比最大为 2.47%， 小于5%为正常。		

39	GX-B1539/22-2-25004	2025. 4. 10	除坐姿司机室基本出入口高度小于1300mm外，其余所检项目合格。	
40	GX-B1539/22-2-25005	2025. 4. 10	除坐姿司机室基本出入口高度小于1300mm外，其余所检项目合格。	

41	GX-B1539/22-2-25006	2025. 4. 10	除坐姿司机室基本出入口高度小于1300mm外，其余所检项目合格。	
42	GX-B1539/22-2-25007	2025. 4. 10	除坐姿司机室基本出入口高度小于1300mm外，其余所检项目合格。	

43	GX-B1499/23-2-25010	2025. 4. 10	所检项目合格。		
44	GX-B1499/23-2-25011	2025. 4. 10	所检项目合格。		

45	GX-B1499/23-2-25012	2025. 4. 10	所检项目合格。	
46	GX-B1309/21-2-25009	2025. 4. 10	所检项目合格。	

47	GX-B1309/21-2-25010	2025. 4. 10	所检项目合格。	
48	GX-B1500/21-2-25036	2025. 4. 10	综合判定：合格。	

49	GX-B1500/21-2-25037	2025. 4. 10	综合判定：合格。	
50	GX-B1500/21-2-25038	2025. 4. 10	综合判定：合格。	

51	GX-B1500/21-2-25039	2025. 4. 10	综合判定：合格。	
52	GX-B1500/21-2-25040	2025. 4. 10	综合判定：合格。	

53	GX-B1500/21-2-25041	2025. 4. 10	综合判定：合格。	
54	GX-B1500/21-2-25042	2025. 4. 10	综合判定：合格。	

55	GX-B1500/21-2-25043	2025. 4. 10	综合判定：合格。	
56	GX-B1451/20-2-25244~25252	2025. 4. 9	本次共检继电保护装置9台，9台继电保护装置所检项目合格。	

57	GX-B1319/21-2-25006~25009	2025. 4. 9	本次共检高压交流断路器4台，4台高压交流断路器所检项目合格。	
58	GX-B1451/20-2-25156~25179	2025. 4. 9	本次共检高压开关柜24台，24台所检项目合格。	

59	GX-B1598/24-2-25071	2025/4/10	实测钢丝绳有效截面积 损失百分比最大为 4.94%，小于5%为正常。	
60	GX-B1598/24-2-25072	2025/4/10	实测钢丝绳有效截面积 损失百分比最大为 4.97%，小于5%为正常。	

61	GX-B1598/24-2-25073	2025/4/10	实测钢丝绳有效截面积 损失百分比最大为 1.38%，小于5%为正常。	
62	GX-B1598/24-2-25074	2025/4/10	实测钢丝绳有效截面积 损失百分比最大为 1.29%，小于5%为正常。	


63	GX-B1598/24-2-25075	2025/4/10	实测钢丝绳有效截面积 损失百分比最大为 1.17%，小于5%为正常。	
64	GX-B1598/24-2-25076	2025/4/10	实测钢丝绳有效截面积 损失百分比最大为 1.18%，小于5%为正常。	

65	GX-B1350/21-2-25013	2025/4/10	本次共检接地装置 10处，10处接地装置所 检项目合格。			
66	GX-B1329/21-2-25116~25121	2025/4/10	本次共检氧化锌避雷器6 组，6组所检项目合格。			

67	GX-B1310/21-2-25051	2025/4/10	符合标准要求。	
68	GX-B1428/21-2-25051	2025/4/10	无缺陷痕迹显示。	

69	GX-B1310/21-2-25052	2025/4/10	符合标准要求。	
70	GX-B1428/21-2-25052	2025/4/10	无缺陷迹痕显示。	

71	GX-B1310/21-2-25046	2025/4/10	符合标准要求。		
72	GX-B1428/21-2-25046	2025/4/10	无缺陷迹痕显示。		

73	GX-B1310/21-2-25053	2025/4/10	符合标准要求。			
74	GX-B1310/21-2-25054	2025/4/10	符合标准要求。			

75	GX-B1428/21-2-25054	2025/4/10	符合标准要求。	 A photograph showing two workers in red hard hats and reflective safety vests. They are in a dark environment, possibly a tunnel or a confined space, with their headlamps on. The date 2025/03/23 is visible in the bottom right corner of the image.
76	GX-B1322/21-2-25120~25123	2025. 4. 11	所检项目合格。	 A photograph showing workers in a room with electrical equipment. One worker in a red hard hat and light-colored uniform is standing, while another is kneeling. There are electrical cabinets and equipment on the floor. The date 2025/03/23 is visible in the bottom right corner of the image.

77	GX-B1313/21-2-25067~25068	2025. 4. 11	所检项目合格。	
78	GX-B1350/21-2-25010	2025. 4. 11	所检项目合格。	


79	GX-B1305/21-2-25001	2025/4/11	综合判定：合格。	 A photograph showing two workers in a tunnel. One worker is wearing a blue uniform and a red helmet, holding a clipboard. The other worker is wearing a grey uniform and a red helmet, standing next to a large piece of equipment. The tunnel walls are rough and there are some cables hanging from the ceiling. A date stamp '2025/03/08' is visible in the bottom right corner of the photo.
80	GX-B1428/21-2-25059	2025/4/10	无缺陷痕迹显示。	 A photograph showing a worker in a grey uniform and a red helmet, wearing a face mask, inspecting a large fan or turbine. The worker is holding a flashlight. The fan has a large circular frame with multiple blades. A date stamp '2025/03/08' is visible in the bottom right corner of the photo.

81	GX-B1428/21-2-25060	2025/4/10	无缺陷迹痕显示。	
82	GX-B1428/21-2-25061	2025/4/10	无缺陷迹痕显示。	

83	GX-B1310/21-2-25062	2025/4/10	符合标准要求。	
84	GX-B1310/21-2-25063	2025/4/10	符合标准要求。	

85	GX-B1310/21-2-25064	2025/4/10	符合标准要求。	 2025/03/09
86	GX-B1310/21-2-25065	2025/4/10	符合标准要求。	 2025/03/08

87	GX-B1310/21-2-25066	2025/4/10	符合标准要求。	
88	GX-B1598/24-2-25065	2025/4/11	实测钢丝绳有效截面积 损失百分比最大为 0.23%，小于5%为正常。	

89	GX-B1598/24-2-25066	2025/4/11	实测钢丝绳有效截面积 损失百分比最大为 0.24%，小于5%为正常。	
90	GX-B1598/24-2-25067	2025/4/11	实测钢丝绳有效截面积 损失百分比最大为 0.75%，小于5%为正常。	

91	GX-B1598/24-2-25068	2025/4/11	实测钢丝绳有效截面积 损失百分比最大为 0.87%，小于5%为正常。	
92	GX-B1598/24-2-25061	2025/4/11	实测钢丝绳有效截面积 损失百分比最大为 2.72%，小于5%为正常。	

93	GX-B1598/24-2-25062	2025/4/11	实测钢丝绳有效截面积 损失百分比最大为 2.06%，小于5%为正常。	
94	GX-B1598/24-2-25063	2025/4/11	实测钢丝绳有效截面积 损失百分比最大为 3.06%，小于5%为正常。	

95	GX-B1598/24-2-25064	2025/4/11	实测钢丝绳有效截面积 损失百分比最大为 2.02%，小于5%为正常。	
96	GX-B1304/21-2-25005	2025. 4. 13	综合判定：合格。	

97	GX-B1304/21-2-25006	2025. 4. 13	综合判定：合格。	 A photograph showing two workers in grey uniforms and red hard hats standing in a large industrial facility. They are positioned next to a large, dark-colored cylindrical machine component. The date '2025/3/30' is visible in the bottom right corner of the image.
98	GX-B1304/21-2-25007	2025. 4. 13	综合判定：合格。	 A photograph showing two workers in grey uniforms and red hard hats standing in a large industrial facility. They are positioned next to a large, dark-colored cylindrical machine component. The date '2025/4/1' is visible in the bottom right corner of the image.

99	GX-B1304/21-2-25008	2025. 4. 13	综合判定：合格。	
100	GX-B1304/21-2-25009	2025. 4. 13	综合判定：合格。	

101	GX-B1304/21-2-25010	2025. 4. 13	综合判定：合格。	
-----	---------------------	-------------	----------	---