

序号	报告编号	发布日期	结论	影像资料
1	GX-B1522/20-7-24001	2024. 3. 1	所检项目合格。	 A photograph showing three workers wearing hard hats and safety vests standing next to a yellow excavator on a dirt construction site. The date stamp '2024/2/27' is visible in the bottom right corner.
2	GX-B1522/20-7-24002	2024. 3. 1	所检项目合格。	 A photograph showing three workers wearing hard hats and safety vests standing next to a yellow excavator on a dirt construction site. The date stamp '2024/2/27' is visible in the bottom right corner.
3	GX-B1522/20-7-24003	2024. 3. 1	所检项目合格。	 A photograph showing three workers wearing hard hats and safety vests standing next to a yellow excavator on a dirt construction site. The date stamp '2024/2/27' is visible in the bottom right corner.

4	GX-B1522/20-7-24004	2024. 3. 1	所检项目合格。		
5	GX-B1517/20-7-24001	2024. 3. 1	综合判定：合格		
6	GX-B1517/20-7-24002	2024. 3. 1	综合判定：合格		