

序号	报告编号	发布日期	结论	影像资料
31	GX-B1424/20-5-24019	2024/3/5	依据NB/T 10176-2019 单轨吊车所检项目合格。 。	
32	GX-B1424/20-5-24020	2024/3/5	依据NB/T 10176-2019 单轨吊车所检项目合格。 。	

33	GX-B1424/20-5-24021	2024/3/5	依据NB/T 10176-2019 单轨吊车所检项目合格。 。	
34	GX-B1424/20-5-24022	2024/3/5	依据NB/T 10176-2019 单轨吊车所检项目合格。 。	

35	GX-B1424/20-5-24023	2024/3/5	依据NB/T 10176-2019 单轨吊车所检项目合格。 。	 2024/2/6
36	GX-B1424/20-5-24024	2024/3/5	依据NB/T 10176-2019 单轨吊车所检项目合格。 。	 2024/2/6

37	GX-B1310/21-5-24038	2024/3/11	符合标准要求。	
38	GX-B1310/21-5-24035	2024. 3. 11	符合标准要求。	


39	GX-B1310/21-5-24036	2024. 3. 11	符合标准要求。		
40	GX-B1310/21-5-24037	2024. 3. 11	符合标准要求。		

41	GX-B1310/21-5-24042	2024. 3. 7	符合标准要求。	
42	GX-B1310/21-5-24043	2024. 3. 7	符合标准要求。	

43	GX-B1328/20-5-24029	2024. 3. 12	本次共检验电器40支， 40支验电器合格。	
44	GX-B1328/20-5-24030	2024. 3. 12	本次共检便携式接地和 接地短路装置40套，40 套便携式接地和接地短 路装置合格。	

45	GX-B1328/20-5-24031	2024. 3. 12	本次共检绝缘杆10支， 10支绝缘杆合格。	
46	GX-B1323/21-5-24005-24010	2024. 3. 12	所检项目合格	


47	GX-B1323/21-5-24011-24014	2024. 3. 12	所检项目合格	
48	GX-B1323/21-5-24015-24018	2024. 3. 12	所检项目合格	

49	GX-B1323/21-5-24019-24023	2024. 3. 12	所检项目合格		
50	GX-B1323/21-5-24024-24028	2024. 3. 12	所检项目合格		

51	GX-B1323/21-5-24029-24037	2024. 3. 12	所检项目合格	
52	GX-B1323/21-5-24038-24042	2024. 3. 12	所检项目合格	

53	GX-B1323/21-5-24043-24049	2024. 3. 12	所检项目合格		
54	GX-B1515/22-5-24004	2024. 3. 13	所检项目合格。		

55	GX-B1328/20-5-24032	2024. 3. 12	本次共检便携式接地和接地短路装置5套，5套便携式接地和接地短路装置合格。	
56	GX-B1328/20-5-24033	2024. 3. 12	本次共检验电器5套，5套验电器合格。	


57	GX-B1328/20-5-24034	2024. 3. 13	本次共检绝缘手套 6只，6只绝缘手套合格。 。	
58	GX-B1328/20-5-24035	2024. 3. 13	本次共检绝缘鞋6只，6 只绝缘鞋合格。	

59	GX-B1416/22-5-24007	2024. 3. 13	综合判定：合格。	
60	GX-B1416/22-5-24008	2024. 3. 13	综合判定：合格。	

61	GX-B1416/22-5-24009	2024. 3. 13	综合判定：合格。	
62	GX-B1416/22-5-24010	2024. 3. 13	综合判定：合格。	

63	GX-B1416/22-5-24011	2024. 3. 13	综合判定：合格。	
64	GX-B1416/22-5-24012	2024. 3. 13	综合判定：合格。	

65	GX-B1416/22-5-24013	2024. 3. 13	综合判定：合格。	
66	GX-B1416/22-5-24014	2024. 3. 13	综合判定：合格。	

67	GX-B1416/22-5-24015	2024. 3. 13	综合判定：合格。		
68	GX-B1416/22-5-24016	2024. 3. 13	综合判定：合格。		

69	GX-B1416/22-5-24017	2024. 3. 13	综合判定：合格。	
70	GX-B1416/22-5-24018	2024. 3. 13	综合判定：合格。	

71	GX-B1309/21-5-24005	2024. 3. 13	合格		
72	GX-B1500/21-5-24025	2024. 3. 13	合格		

73	GX-B1500/21-5-24026	2024. 3. 13	合格	
74	GX-B1500/21-5-24027	2024. 3. 13	合格	

75	GX-B1309/21-5-24006	2024. 3. 13	合格	 HONOR 80 Pro 160MP Matrix Camera 2024.3.13
76	GX-B1500/21-5-24028	2024. 3. 13	合格	 HONOR 80 Pro 160MP Matrix Camera 2024.3.13

77	GX-B1500/21-5-24029	2024. 3. 13	合格		
78	GX-B1500/21-5-24030	2024. 3. 13	合格		

79	GX-B1500/21-5-24031	2024. 3. 13	合格			
80	GX-B1309/21-5-24007	2024. 3. 13	合格			

81	GX-B1500/21-5-24032	2024. 3. 13	合格		 2024. 3. 13	
82	GX-B1500/21-5-24023	2024. 3. 13	合格		 2024. 3. 13	

83	GX-B1500/21-5-24034	2024. 3. 13	合格	
84	GX-B1500/21-5-24035	2024. 3. 13	合格	


85	GX-B1416/22-5-24007	2024/3/13	综合判定：合格。	
86	GX-B1416/22-5-24008	2024/3/13	综合判定：合格。	

87	GX-B1416/22-5-24009	2024/3/13	综合判定：合格。	
88	GX-B1416/22-5-24010	2024/3/13	综合判定：合格。	


89	GX-B1416/22-5-24011	2024/3/13	综合判定：合格。	 2024/2/5
90	GX-B1416/22-5-24012	2024/3/13	综合判定：合格。	 2024/2/5

91	GX-B1416/22-5-24013	2024/3/13	综合判定：合格。	
92	GX-B1416/22-5-24014	2024/3/13	综合判定：合格。	

93	GX-B1416/22-5-24015	2024/3/13	综合判定：合格。		
94	GX-B1416/22-5-24016	2024/3/13	综合判定：合格。		

95	GX-B1416/22-5-24017	2024/3/13	综合判定：合格。	
96	GX-B1416/22-5-24018	2024/3/13	综合判定：合格。	

97	GX-B1328/20-5-24029		本次共检验电器40支， 40支验电器合格。	
98	GX-B1328/20-5-24030		本次共检便携式接地和 接地短路装置40套，40 套便携式接地和接地短 路装置合格。	

99	GX-B1328/20-5-24031		本次共检绝缘杆10支， 10支绝缘杆合格。	
100	GX-B1310/21-5-24046	2024. 3. 14	符合标准要求。	

101	GX-B1310/21-5-24047	2024. 3. 14	符合标准要求。	 2024/02/24
102	GX-B1310/21-5-24048	2024. 3. 14	符合标准要求。	 2024/02/24

103	GX-B1310/21-5-24049	2024. 3. 14	符合标准要求。	 A worker wearing a blue jacket, red helmet, and orange safety harness is working on a red metal structure. The date 2024/02/24 is visible in the bottom right corner of the photo.
104	GX-B1310/21-5-24050	2024. 3. 14	符合标准要求。	 Two workers wearing blue jackets and red helmets are working on a large metal structure. One worker is on a ladder. The date 2024/02/25 is visible in the bottom right corner of the photo.

105	GX-B1310/21-5-24051	2024. 3. 14	符合标准要求。	
106	GX-B1310/21-5-24052	2024. 3. 14	符合标准要求。	

107	GX-B1310/21-5-24053	2024. 3. 14	符合标准要求。	
108	GX-B1310/21-5-24054	2024. 3. 14	符合标准要求。	

109	GX-B1495/20-5-24224~24230	2024. 3. 14	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	
110	GX-B1495/20-5-24231~24240	2024. 3. 14	本次共检高压开关柜10台，10台高压开关柜所检项目合格。	

111	GX-B1321/20-5-24162~24167	2024. 3. 14	本次共检电力电缆 6条，6条电力电缆所检 项目合格。	
112	GX-B1321/20-5-24168~24174	2024. 3. 14	本次共检电力电缆 7条，7条电力电缆所检 项目合格。	