



序号		发布日期	结论	影像资料
114	GX-B1495/20-1-241105~241114	2024. 5. 24	本次共检高压开关设备10台，10台高压开关设备所检项目合格	 A photograph showing an inspection of high-voltage switchgear. Two men are visible: one is kneeling on the floor, possibly using a tool or measuring device, while the other stands nearby. The equipment is a large, metal cabinet with a door open, revealing internal components. A yellow date stamp '2024/04/25' is visible in the bottom left corner of the image.
115	GX-B1351/21-1-24007~24008	2024. 5. 23	本次共检矿用隔爆型检漏继电器2台, 2台所检项目合格	 A photograph of a worker in a yellow protective suit and red helmet inspecting a piece of electrical equipment. The worker is kneeling on a green mat, holding a device. The equipment is a large metal cabinet with a door open, showing internal components. A yellow date stamp '2024/5/24' is visible in the bottom right corner of the image.

116	GX-B1352/21-1-245016	2024. 5. 23	所检项目合格	 A worker wearing a brown jacket and a red helmet is operating a piece of machinery at night. The scene is illuminated by a bright light source, possibly a work lamp. The worker is looking towards the camera. A yellow timestamp "2024/4/24" is visible in the bottom right corner of the image.
117	GX-B1499/23-1-24010	2024. 5. 27	所检项目合格	 A worker wearing a light-colored short-sleeved shirt and a red helmet is standing on a metal platform. The worker is looking towards the camera. The background shows a brick wall and a metal structure. A red timestamp "2024/5/27" is visible in the bottom right corner of the image.

118	GX-B1499/23-1-24011	2024. 5. 27	所检项目合格	
119	GX-B1300/23-1-24004	2024/5/29	合格	

120	GX-B1415/22-1-24005	2024. 5. 29	综合判定：合格			
121	GX-B1415/22-1-24006	2024. 5. 29	综合判定：合格			


122	GX-B1321/20-1-24649~24653	2024. 5. 29	本次共检电力电缆5条，5条电力电缆所检项目合格	
123	GX-B1321/20-1-24654~24657	2024. 5. 29	本次共检电力电缆4条，4条电力电缆所检项目合格	

124	GX-B1307/20-1-24028	2024. 5. 29	综合判定：合格	
125	GX-B1307/20-1-24029	2024. 5. 29	综合判定：合格	


126	GX-B1307/20-1-24030	2024. 5. 29	综合判定：合格	
127	GX-B1307/20-1-24031	2024. 5. 29	综合判定：合格	



128	GX-B1307/20-1-24032	2024. 5. 29	综合判定：合格	
129	GX-B1307/20-1-24033	2024. 5. 29	综合判定：合格	

130	GX-B1307/20-1-24034	2024. 5. 29	综合判定：合格	
131	GX-B1310/21-1-24074	2024. 5. 30	符合标准要求	

132	GX-B1310/21-1-24075	2024. 5. 30	符合标准要求	
133	GX-B1310/21-1-24076	2024. 5. 30	符合标准要求	

134	GX-B1310/21-1-24077	2024. 5. 30	符合标准要求	
135	GX-B1310/21-1-24082	2024. 5. 30	符合标准要求	

136	GX-B1427/21-1-24082	2024. 5. 30	符合标准要求	
137	GX-B1310/21-1-24083	2024. 5. 30	符合标准要求	


138	GX-B1427/21-1-24083	2024. 5. 30	符合标准要求	 <p>A photograph showing industrial machinery, possibly a forklift or similar equipment, enclosed within a metal safety cage. The cage is made of vertical bars and a mesh. The background shows a factory or workshop environment with various pipes and structures. A red date stamp '2024/5/22' is visible in the bottom right corner of the image.</p>
139	GX-B1428/21-1-24084	2024. 5. 30	符合标准要求	 <p>A close-up photograph of a highly reflective, metallic surface, likely a part of industrial machinery. The surface is dark and shows a bright reflection of light, creating a distorted, circular shape. A red date stamp '2024/5/22' is visible in the bottom right corner of the image.</p>

140	GX-B1310/21-1-24085	2024. 5. 30	符合标准要求	 <p>2024.05.24 09:33</p> <p>2024/5/24</p>
141	GX-B1428/21-1-24085	2024. 5. 30	符合标准要求	 <p>2024.05.24 09:26</p> <p>2024/5/24</p>

142	GX-B1310/21-1-24086	2024. 5. 30	符合标准要求	
143	GX-B1428/21-1-24086	2024. 5. 30	符合标准要求	


144	GX-B1428/21-1-24087	2024. 5. 30	符合标准要求	
145	GX-B1310/21-1-24078	2024. 5. 30	符合标准要求	

146	GX-B1310/21-1-24079	2024. 5. 30	符合标准要求	
147	GX-B1310/21-1-24080	2024. 5. 30	符合标准要求	

148	GX-B1310/21-1-24081	2024. 5. 30	符合标准要求			
149	GX-B1428/21-1-24084	2024. 5. 30	无缺陷迹痕显示			


150	GX-B1310/21-1-24085	2024. 5. 30	符合标准要求	 <p>2024.05.24 09:33</p> <p>2024/5/24</p>
151	GX-B1428/21-1-24085	2024. 5. 30	无缺陷迹痕显示	 <p>2024.05.24 09:26</p> <p>2024/5/24</p>

152	GX-B1310/21-1-24086	2024. 5. 30	符合标准要求	
153	GX-B1428/21-1-24086	2024. 5. 30	无缺陷迹痕显示	

154	GX-B1428/21-1-24087	2024. 5. 30	无缺陷迹痕显示	
155	GX-B1332/21-1-24043~24066	2024. 5. 28	本次共检电力电容器 24台，24台所检项目 合格	

156	GX-B1310/21-1-24078	2024. 5. 30	符合标准要求	
157	GX-B1310/21-1-24079	2024. 5. 30	符合标准要求	

158	GX-B1310/21-1-24080	2024. 5. 30	符合标准要求	 <p>2024/5/21</p>
159	GX-B1310/21-1-24081	2024. 5. 30	符合标准要求	 <p>2024/5/2</p>

160	GX-B1428/21-1-24084	2024. 5. 30	符合标准要求	 <p>2024/5/22</p>
161	GX-B1310/21-1-24085	2024. 5. 30	符合标准要求	 <p>2024/05/24 09:33</p> <p>2024/5/24</p>

162	GX-B1428/21-1-24085	2024. 5. 30	符合标准要求	
163	GX-B1310/21-1-24086	2024. 5. 30	符合标准要求	

164	GX-B1428/21-1-24086	2024. 5. 30	符合标准要求	
165	GX-B1428/21-1-24087	2024. 5. 30	无缺陷迹痕显示	

23045

