

序号	报告编号	发布日期	结论	影像资料
1	GX-B1366/20-A-24091	2024/9/2	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
2	GX-B1366/20-A-24090	2024/9/2	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
3	GX-B1366/20-A-24089	2024/9/2	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
4	GX-B1365/20-A-24068	2024/9/2	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
5	GX-B1365/20-A-24067	2024/9/2	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
6	GX-B1364/22-A-241013	2024/9/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
7	GX-B1364/22-A-241012	2024/9/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
8	GX-B1366/20-A-24088	2024/9/2	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
9	GX-B1365/20-A-24066	2024/9/2	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
10	GX-B1364/22-A-241000	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
11	GX-B1364/22-A-24999	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
12	GX-B1364/22-A-24995	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
13	GX-B1364/22-A-24994	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
14	GX-B1364/22-A-24993	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
15	GX-B1364/22-A-24992	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
16	GX-B1364/22-A-24991	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
17	GX-B1364/22-A-24990	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
18	GX-B1363/22-A-24440	2024/9/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
19	GX-B1363/22-A-24441	2024/9/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
20	GX-B1363/22-A-24452	2024/9/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
21	GX-B1363/22-A-24451	2024/9/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
22	GX-B1363/22-A-24454	2024/9/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
23	GX-B1363/22-A-24455	2024/9/2	所检项目合格。	 A photograph showing two male technicians in light blue work shirts inspecting a large, dark-colored industrial furnace. The furnace has two doors, one of which is open. A white vertical chimney pipe extends from the top of the furnace. The technicians are wearing gloves and looking into the furnace. A yellow warning label is visible on the right door. The background shows a window with a view of trees outside. A date stamp '2024.08.27' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
24	GX-B1364/22-A-241031	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
25	GX-B1364/22-A-241030	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1364/22-A-241029	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
27	GX-B1364/22-A-241028	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1364/22-A-241027	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
29	GX-B1538/22-A-24087	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1364/22-A-241008	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1364/22-A-241009	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1364/22-A-241001	2024/9/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
33	GX-B1363/22-A-24458	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1363/22-A-24459	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
35	GX-B1363/22-A-24460	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1363/22-A-24457	2024/9/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
37	GX-B1364/22-A-241010	2024/9/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1364/22-A-241007	2024/9/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
39	GX-B1364/22-A-241017	2024/9/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1364/22-A-241014	2024/9/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
41	GX-B1364/22-A-241015	2024/9/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1364/22-A-241016	2024/9/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1363/22-A-24463	2024/9/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1363/22-A-24464	2024/9/6	所检项目合格。	 A photograph showing two male technicians in light blue uniforms inspecting a large, rusted industrial furnace. One technician is wearing yellow gloves. A large vertical pipe is attached to the top of the furnace. A green floor fan is visible on the right. A date stamp '2024/09/02' is in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
45	GX-B1363/22-A-24468	2024/9/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1363/22-A-24469	2024/9/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
47	GX-B1363/22-A-24470	2024/9/6	所检项目合格。	 A photograph showing two male technicians in grey work shirts and dark trousers inspecting a large, rusted industrial furnace. The furnace has a tall vertical pipe on top and several yellow warning triangles. One technician is on the left, looking at the furnace, and the other is on the right, wearing gloves and using a tool. A green floor fan is visible on the right. The date stamp '2024/09/04' is in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
48	GX-B1363/22-A-24471	2024/9/6	所检项目合格。	 A photograph showing two male technicians in grey uniforms inspecting a large, rusted industrial furnace. One technician is on the left, looking into the furnace's opening, while the other is on the right, wearing gloves and touching the interior. The furnace has a large vertical pipe on top and yellow warning triangles. A green floor fan is on the right. A date stamp '2024/09/04' is in the bottom right corner of the photo.