


序号	报告编号	发布日期	结论	影像资料
179	GX-B1427/21-6-24074	2024/9/29	符合标准要求	 A worker wearing a red hard hat, safety glasses, and a grey safety harness is working on a metal structure. The worker is holding a tool or device. The background shows industrial equipment. A timestamp "2024 09 04" is visible in the bottom right corner of the image.
180	GX-B1427/21-6-24075	2024/9/29	符合标准要求	 A worker wearing a red hard hat and a blue safety harness is standing next to a yellow forklift. The worker is looking towards the camera. The background shows industrial equipment. A timestamp "2024 09 06" is visible in the bottom right corner of the image.

181	GX-B1427/21-6-24076	2024/9/29	符合标准要求	 A worker in blue overalls and a red helmet is working on a vertical metal structure, possibly a part of a machine or a building frame. The worker is positioned on a platform, and the structure is made of dark metal beams. The date 2024 09 05 is visible in the bottom right corner of the image.
182	GX-B1427/21-6-24077	2024/9/29	符合标准要求	 A worker in a white shirt and a red helmet is working on a vertical metal structure. The worker is wearing a blue harness and is using a tool to work on the structure. The date 2024 09 07 is visible in the bottom right corner of the image.
183	GX-B1427/21-6-24078	2024/9/29	符合标准要求	 A worker in blue overalls and a red helmet is working on a vertical metal structure. The worker is positioned on a platform, and the structure is made of dark metal beams. The date 2024 09 05 is visible in the bottom right corner of the image.

184	GX-B1427/21-6-24079	2024/9/29	符合标准要求	 A worker in a blue uniform and red helmet is working on a vertical structure, possibly a ladder or scaffolding. The worker is wearing a safety harness and a headlamp. The date 2024 09 06 is visible in the bottom right corner of the image.
185	GX-B1427/21-6-24080	2024/9/29	符合标准要求	 A worker in a white shirt and red helmet is working on a vertical structure, possibly a ladder or scaffolding. The worker is wearing a safety harness and a headlamp. The date 2024 09 07 is visible in the bottom right corner of the image.
186	GX-B1310/21-6-24303	2024/9/29	符合标准要求	 A worker in a grey shirt and red helmet is working on a large red machine, possibly a pump or motor. The worker is wearing a safety harness and a headlamp. The date 2024 08 31 is visible in the bottom right corner of the image.

187	GX-B1427/21-6-24092	2024/9/29	符合标准要求	 2024 08 31
188	GX-B1310/21-6-24304	2024/9/29	符合标准要求	 2024 08 31
189	GX-B1310/21-6-24305	2024/9/29	符合标准要求	 2024 08 31


190	GX-B1427/21-6-24093	2024/9/30	符合标准要求	
191	GX-B1427/21-6-24094	2024/9/30	符合标准要求	
192	GX-B1427/21-6-24095	2024/9/30	符合标准要求	

193	GX-B1310/21-6-24309	2024/9/30	符合标准要求	
194	GX-B1310/21-6-24310	2024/9/30	符合标准要求	
195	GX-B1310/21-6-24311	2024/9/30	符合标准要求	

196	GX-B1310/21-6-24312	2024/9/30	符合标准要求	 A worker wearing a red hard hat and safety glasses is operating a large blue industrial machine. The machine has various pipes and components. The date '2024 09 09' is visible in the bottom right corner of the photo.
197	GX-B1310/21-6-24313	2024/9/30	符合标准要求	 A worker wearing a red hard hat and safety glasses is inspecting a large industrial structure. The structure appears to be a large pipe or duct. The date '2024 09 09' is visible in the bottom right corner of the photo.
198	GX-B1310/21-6-24314	2024/9/30	符合标准要求	 A worker wearing a red hard hat and safety glasses is standing next to a large industrial machine. The machine has a large cylindrical component. The date '2024 09 09' is visible in the bottom right corner of the photo.

199	GX-B1310/21-6-24315	2024/9/30	符合标准要求	 A worker in a blue uniform and red helmet is inspecting a large, blue, cylindrical industrial component with a circular opening containing many small holes. The date 2024 09 10 is visible in the bottom right corner of the image.
200	GX-B1310/21-6-24316	2024/9/30	符合标准要求	 A worker in a blue uniform and red helmet is standing on a yellow lift, inspecting a blue industrial structure. The date 2024 09 10 is visible in the bottom right corner of the image.
201	GX-B1310/21-6-24317	2024/9/30	符合标准要求	 A worker in a blue uniform and red helmet is inspecting a large, dark, rectangular metal component. The date 2024 09 10 is visible in the bottom right corner of the image.

202	GX-B1304/21-6-24045	2024/9/29	综合判定合格	
203	GX-B1303/21-6-24035	2024/9/29	综合判定合格	
204	GX-B1303/21-6-24036	2024/9/29	综合判定合格	

205	GX-B1303/21-6-24037	2024/9/29	综合判定合格	
206	GX-B1303/21-6-24038	2024/9/29	综合判定合格	
207	GX-B1304/21-6-24044	2024/9/30	综合判定:合格。	

208	GX-B1304/21-6-24042	2024/9/30	综合判定合格	
209	GX-B1304/21-6-24046	2024/9/30	综合判定合格	