

| 序号 | 报告编号                | 发布日期        | 结论      | 影像资料   |
|----|---------------------|-------------|---------|--|
| 22 | GX-B1422/23-2-25001 | 2025. 2. 21 | 综合判定：合格 |  <p>2025/02/08</p>  |
| 23 | GX-B1422/23-2-25002 | 2025. 2. 21 | 综合判定：合格 |  <p>2025/02/08</p> |


|    |                     |             |         |  |
|----|---------------------|-------------|---------|--|
| 24 | GX-B1422/23-2-25003 | 2025. 2. 21 | 综合判定：合格 |  <p>2025/02/08</p>  |
| 25 | GX-B1422/23-2-25004 | 2025. 2. 21 | 综合判定：合格 |  <p>2025/02/08</p>  |
| 26 | GX-B1422/23-2-25005 | 2025. 2. 21 | 综合判定：合格 |  <p>2025/02/08</p> |

|    |                     |             |         |  |
|----|---------------------|-------------|---------|--|
| 27 | GX-B1422/23-2-25006 | 2025. 2. 21 | 综合判定：合格 |  <p>2025/02/03</p>  |
| 28 | GX-B1612/23-2-25006 | 2025/2/21   | 所检项目合格。 |  <p>2025/01/20</p>  |
| 29 | GX-B1611/23-2-25001 | 2025/2/19   | 所检项目合格。 |  <p>2025/01/20</p> |

|    |                     |             |                                      |  |
|----|---------------------|-------------|--------------------------------------|--|
| 30 | GX-B1310/21-2-25018 | 2025/2/20   | 符合标准要求。                              |   |
| 31 | GX-B1427/21-2-25018 | 2025/2/20   | 符合标准要求。                              |   |
| 32 | GX-B1328/20-2-25015 | 2025. 2. 21 | 本次共检便携式接地和接地短路装置1套，1套便携式接地和接地短路装置合格。 |  |

|    |                     |             |         |  |  |  |
|----|---------------------|-------------|---------|--|--|--|
| 33 | GX-B1310/21-2-25016 | 2025. 2. 17 | 符合标准要求。 |  |  <p>2025/01/19</p>  |  |
| 34 | GX-B1427/21-2-25016 | 2025. 2. 17 | 符合标准要求。 |  |  <p>2025/01/19</p>  |  |
| 35 | GX-B1310/21-2-25017 | 2025. 2. 17 | 符合标准要求。 |  |  <p>2025/01/19</p> |  |

|    |                     |             |         |  |  |  |
|----|---------------------|-------------|---------|--|--|--|
| 36 | GX-B1427/21-2-25017 | 2025. 2. 17 | 符合标准要求。 |  |   |  |
| 37 | GX-B1350/21-2-25003 | 2025. 2. 21 | 所检项目合格。 |  |   |  |
| 38 | GX-B1350/21-2-25004 | 2025. 2. 21 | 所检项目合格。 |  |  |  |

|    |                           |             |         |  |  |
|----|---------------------------|-------------|---------|--|--|
| 39 | GX-B1352/21-2-25001~25010 | 2025. 2. 18 | 所检项目合格。 | <br>2025/02/13  |  |
| 40 | GX-B1352/21-2-25011~25018 | 2025. 2. 18 | 所检项目合格。 | <br>2025/02/13  |  |
| 41 | GX-B1352/21-2-25019~25029 | 2025. 2. 18 | 所检项目合格。 | <br>2025/02/14 |  |

|    |                           |             |         |  |  |  |
|----|---------------------------|-------------|---------|--|--|--|
| 42 | GX-B1352/21-2-25030~25040 | 2025. 2. 18 | 所检项目合格。 |  |   |  |
| 43 | GX-B1359/21-2-25007~25008 | 2025. 2. 18 | 所检项目合格。 |  |   |  |
| 44 | GX-B1359/21-2-25009~25011 | 2025. 2. 18 | 所检项目合格。 |  |  |  |

|    |                     |           |          |  |
|----|---------------------|-----------|----------|--|
| 45 | GX-B1422/23-2-25007 | 2025/2/24 | 综合判定：合格。 |   |
| 46 | GX-B1422/23-2-25008 | 2025/2/24 | 综合判定：合格。 |   |
| 47 | GX-B1422/23-2-25009 | 2025/2/24 | 综合判定：合格。 |  |

|    |                     |           |          |  |  |
|----|---------------------|-----------|----------|--|--|
| 48 | GX-B1422/23-2-25010 | 2025/2/24 | 综合判定：合格。 |  <p>2025/02/09</p>  |  |
| 49 | GX-B1422/23-2-25011 | 2025/2/24 | 综合判定：合格。 |  <p>2025/02/09</p>  |  |
| 50 | GX-B1422/23-2-25012 | 2025/2/24 | 综合判定：合格。 |  <p>2025/02/09</p> |  |

|    |                     |             |         |  |
|----|---------------------|-------------|---------|--|
| 51 | GX-B1515/22-2-25010 | 2025. 2. 25 | 所检项目合格。 |   |
| 52 | GX-B1328/20-2-25011 | 2025. 2. 24 | 所检项目合格。 |   |
| 53 | GX-B1328/20-2-25012 | 2025. 2. 24 | 所检项目合格。 |  |

|    |                           |             |                                  |  |
|----|---------------------------|-------------|----------------------------------|--|
| 54 | GX-B1328/20-2-25013       | 2025. 2. 24 | 所检项目合格。                          |   |
| 55 | GX-B1328/20-2-25014       | 2025. 2. 24 | 所检项目合格。                          |   |
| 56 | GX-B1359/21-2-25001~25002 | 2025. 2. 26 | 本次共检矿用隔爆型照明信号综合保护装置2台, 2台所检项目合格。 |  |

|    |                           |             |                                  |  |  |  |
|----|---------------------------|-------------|----------------------------------|--|--|--|
| 57 | GX-B1359/21-2-25003~25006 | 2025. 2. 26 | 本次共检矿用隔爆型照明信号综合保护装置4台,4台所检项目合格。  |  |   |  |
| 58 | GX-B1352/21-2-25067~25085 | 2025. 2. 26 | 本次共检矿用防爆低压交流真空馈电开关19台,19台所检项目合格。 |  |   |  |
| 59 | GX-B1352/21-2-25041~25066 | 2025. 2. 26 | 本次共检矿用防爆低压交流真空馈电开关26台,26台所检项目合格。 |  |  |  |

|    |                     |             |                           |  |
|----|---------------------|-------------|---------------------------|--|
| 60 | GX-B1328/20-2-25010 | 2025. 2. 26 | 所检项目合格。                   |   |
| 61 | GX-B1328/20-2-25016 | 2025. 2. 26 | 所检项目合格。                   |   |
| 62 | GX-B1350/21-2-25001 | 2025/2/26   | 本次共检验接地装置4处，4处接地装置所检项目合格。 |  |

|    |                           |             |                           |  |
|----|---------------------------|-------------|---------------------------|--|
| 63 | GX-B1350/21-2-25002       | 2025/2/26   | 本次共检验接地装置3处，3处接地装置所检项目合格。 |   |
| 64 | GX-B1329/21-2-25039~25056 | 2025. 2. 26 | 本次共检氧化锌避雷器18组，18组所检项目合格。  |   |
| 65 | GX-B1329/21-2-25031~25038 | 2025. 2. 26 | 本次共检氧化锌避雷器8组，8组所检项目合格。    |  |