

序号	报告编号	发布日期	结论	影像资料	
266	GX-B1309/21-6-25006	2025/4/10	符合标准要求		 A worker in a blue uniform and red helmet is working on a large pipe in a tunnel. The worker is using a tool to inspect or work on the pipe. The background shows the interior of a tunnel with other pipes and structural elements. A timestamp '2025 03 20' is visible in the bottom right corner of the image.
267	GX-B1309/21-6-25007	2025/4/10	符合标准要求		 A worker in a grey uniform and red helmet is standing in a tunnel. The worker is holding a clipboard and looking towards the camera. The background shows the interior of a tunnel with large pipes and structural elements. A timestamp '2025 03 29' is visible in the bottom right corner of the image.


268	GX-B1309/21-6-25008	2025/4/11	所检项目合格。			
269	GX-B1500/21-6-25039	2025/4/10	符合标准要求			
270	GX-B1500/21-6-25040	2025/4/10	符合标准要求			

271	GX-B1500/21-6-25041	2025/4/10	符合标准要求	
272	GX-B1500/21-6-25042	2025/4/10	符合标准要求	
273	GX-B1500/21-6-25043	2025/4/10	符合标准要求	

274	GX-B1500/21-6-25044	2025/4/10	符合标准要求			
275	GX-B1500/21-6-25045	2025/4/10	符合标准要求			
276	GX-B1500/21-6-25046	2025/4/10	符合标准要求			

277	GX-B1305-6-25005	2025/4/11	综合判定：合格。	
278	GX-B1539/22-6-25003	2025/4/15	所检项目合格。	
279	GX-B1303/21-6-25002	2025/4/16	合格。	

280	GX-B1303/21-6-25003	2025/4/16	合格。	
281	GX-B1303/21-6-25004	2025/4/16	合格。	
282	GX-B1313/21-6-25077~25085	2025/4/15	本次共检电力变压器9台，9台电力变压器所检项目合格。 。	

283	GX-B1313/21-6-25086~25090	2025/4/15	本次共检电力变压器5台，5台电力变压器所检项目合格。 。	 2025 03 31	
284	GX-B1313/21-6-25091~25099	2025/4/15	本次共检电力变压器9台，9台电力变压器所检项目合格。 。	 2025 04 01	
285	GX-B1313/21-6-25100~25101	2025/4/15	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	 2025 03 22	

286	GX-B1310/21-6-25045	2025/4/11	符合标准要求	
287	GX-B1310/21-6-25046	2025/4/11	符合标准要求	
288	GX-B1310/21-6-25047	2025/4/11	符合标准要求	

289	GX-B1310/21-6-25048	2025/4/11	符合标准要求	
290	GX-B1310/21-6-25049	2025/4/11	符合标准要求	
291	GX-B1310/21-6-25050	2025/4/11	符合标准要求	

292	GX-B1427/21-6-25009	2025/4/11	符合标准要求			
293	GX-B1310/21-6-25039	2025/4/11	符合标准要求			
294	GX-B1310/21-6-25040	2025/4/11	符合标准要求			

295	GX-B1310/21-6-25041	2025/4/11	符合标准要求			
296	GX-B1310/21-6-25042	2025/4/11	符合标准要求			
297	GX-B1310/21-6-25043	2025/4/11	符合标准要求			

298	GX-B1310/21-6-25044	2025/4/11	符合标准要求		
299	GX-B1352/21-6-25233~25241	2025/4/14	本次共检矿用防爆低压交流真空馈电开关9台,9台所检项目合格。		
300	GX-B1359/21-6-25046~25049	2025/4/14	本次共检矿用隔爆型照明信号综合保护装置4台,4台矿用隔爆型照明信号综合保护装置所检项目合格。		

301	GX-B1451/20-6-25352~25358	2025/4/17	本次共检高压开关柜7台,7台高压开关柜所检项目合格。 。			
302	GX-B1304/21-6-25004	2025/4/17	综合判定：合格。			
303	GX-B1328/20-6-25104	2025/4/17	本次共检携带式接地和接地短路装置1套,1套携带式接地和接地短路装置合格。			

304	GX-B1328/20-6-25103	2025/4/17	本次共检验电器1支，1支验电器合格。		
305	GX-B1350/21-6-25018	2025/4/16	本次共检测接地装置3处，3处接地装置所检项目合格。		
306	GX-B1350/21-6-25019	2025/4/16	本次共检测接地装置7处，7处接地装置所检项目合格。		

307	GX-B1427/21-6-25013	2025/4/18	符合标准要求		 2025 03 27
308	GX-B1427/21-6-25014	2025/4/18	符合标准要求		 2025 03 27
309	GX-B1427/21-6-25015	2025/4/18	符合标准要求		 2025 03 28


310	GX-B1427/21-6-25016	2025/4/18	符合标准要求		 A worker wearing a red hard hat, safety glasses, and a grey protective suit with a blue harness is operating a piece of industrial machinery. The date stamp '2025 03 28' is visible in the bottom right corner of the photo.
311	GX-B1427/21-6-25017	2025/4/18	符合标准要求		 A worker wearing a red hard hat, safety glasses, and a grey protective suit with a blue harness is operating a piece of industrial machinery. The date stamp '2025 03 29' is visible in the bottom right corner of the photo.
312	GX-B1427/21-6-25018	2025/4/18	符合标准要求		 A worker wearing a red hard hat, safety glasses, and a grey protective suit with a blue harness is operating a piece of industrial machinery. The date stamp '2025 03 29' is visible in the bottom right corner of the photo.

313	GX-B1427/21-6-25019	2025/4/18	符合标准要求	 A worker wearing a red hard hat, a light-colored protective suit, and a blue safety harness is inspecting a large, dark, vertical industrial structure. The date stamp '2025 03 30' is visible in the bottom right corner of the photo.
314	GX-B1427/21-6-25020	2025/4/18	符合标准要求	 A worker wearing a red hard hat, a dark blue protective suit, and a blue safety harness is inspecting a large, dark, vertical industrial structure. The date stamp '2025 03 31' is visible in the bottom right corner of the photo.
315	GX-B1310/21-6-25069	2025/4/18	符合标准要求	 A worker wearing a red hard hat, a dark blue protective suit, and a blue safety harness is inspecting a large, dark, vertical industrial structure. The date stamp '2025 03 27' is visible in the bottom right corner of the photo.


316	GX-B1310/21-6-25072	2025/4/18	符合标准要求	 A worker wearing a red hard hat and a grey work jacket is operating a large, red industrial machine. The machine has a large, circular opening. The worker is standing on a yellow platform. The date "2025 03 27" is visible in the bottom right corner of the image.
317	GX-B1310/21-6-25075	2025/4/18	符合标准要求	 A worker wearing a blue work jacket and a red hard hat is operating a large industrial machine. The machine has a large, circular opening. The worker is standing on a yellow platform. The date "2025 03 28" is visible in the bottom right corner of the image.
318	GX-B1310/21-6-25078	2025/4/18	符合标准要求	 A worker wearing a blue work jacket and a red hard hat is operating a large industrial machine. The machine has a large, circular opening. The worker is standing on a yellow platform. The date "2025 03 28" is visible in the bottom right corner of the image.


319	GX-B1310/21-6-25081	2025/4/18	符合标准要求			
320	GX-B1310/21-6-25084	2025/4/18	符合标准要求			
321	GX-B1310/21-6-25087	2025/4/18	符合标准要求			

322	GX-B1310/21-6-25090	2025/4/18	符合标准要求			
323	GX-B1310/21-6-25093	2025/4/18	符合标准要求			
324	GX-B1310/21-6-25096	2025/4/18	符合标准要求			


325	GX-B1310/21-6-25070	2025/4/18	符合标准要求		 2025 03 27
326	GX-B1310/21-6-25071	2025/4/18	符合标准要求		 2025 03 27
327	GX-B1310/21-6-25073	2025/4/18	符合标准要求		 2025 03 27


328	GX-B1310/21-6-25074	2025/4/18	符合标准要求		
329	GX-B1310/21-6-25076	2025/4/18	符合标准要求		
330	GX-B1310/21-6-25077	2025/4/18	符合标准要求		

331	GX-B1310/21-6-25079	2025/4/18	符合标准要求			
332	GX-B1310/21-6-25080	2025/4/18	符合标准要求			
333	GX-B1310/21-6-25082	2025/4/18	符合标准要求			

334	GX-B1310/21-6-25083	2025/4/18	符合标准要求			
335	GX-B1310/21-6-25085	2025/4/18	符合标准要求			
336	GX-B1310/21-6-25086	2025/4/18	符合标准要求			

337	GX-B1310/21-6-25088	2025/4/18	符合标准要求			
338	GX-B1310/21-6-25089	2025/4/18	符合标准要求			
339	GX-B1310/21-6-25091	2025/4/18	符合标准要求			

340	GX-B1310/21-6-25092	2025/4/18	符合标准要求	 A worker wearing a red hard hat and a blue safety harness is working on a metal structure. The date stamp '2025 03 30' is visible in the bottom right corner of the image.
341	GX-B1310/21-6-25094	2025/4/18	符合标准要求	 A worker wearing a red hard hat with a headlamp and safety glasses is looking at the camera. The date stamp '2025 03 31' is visible in the bottom right corner of the image.
342	GX-B1310/21-6-25095	2025/4/18	符合标准要求	 A worker wearing a red hard hat and a blue safety harness is working on a metal structure. The date stamp '2025 03 31' is visible in the bottom right corner of the image.

343	GX-B1310/21-6-25097	2025/4/18	符合标准要求	 2025 03 31
344	GX-B1310/21-6-25098	2025/4/18	符合标准要求	 2025 03 31